



ОВОЩЕРЕЗКА HURAKAN HKN-FNT-WSS

| Поз | Наименование детали |
|-----|--------------------------------|
| 1 | Handle |
| 2 | Colloid |
| 3 | Pusher |
| 4 | Small feeder hopper |
| 5 | Hopper |
| 5A | Hopper (die casting) |
| 6 | Seat of magnet |
| 7 | Magnet |
| 8 | Disc |
| 9 | Ejector |
| 10 | Locking handle |
| 10A | Locking handle (die casting) |
| 11 | Pin |
| 12 | Hook |
| 13 | Spring |
| 14 | Hopper lid spindle |
| 15 | Spindle sleeve |
| 16 | Stop collar |
| 17 | Body |
| 17A | Body (die casting) |
| 18 | L type magnet seat |
| 19 | Sleeve pipe |
| 20 | Sleeve |
| 21 | Securing key |
| 22 | Off switch |
| 23 | On switch |
| 24 | Output axis |
| 25 | Bearing cover |
| 26 | Oil seal |
| 27 | Bearing |
| 28 | Bearing |
| 29 | Microswitch |
| 30 | Fixing plate |
| 31 | Belt wheel |
| 32 | Belt |
| 33 | Support of motor |
| 34 | Motor |
| 35 | Cable tie |
| 36 | Power cord |
| 37 | Rubber foot |
| 38 | Bottom plate |
| 39 | Capacitor |
| 40 | Capacitor of clamp |
| 41 | Bottom base |
| 42 | Electric box |
| 43 | Support of electric box |
| 44 | Brush |
| 45 | Spanner |
| 46 | Handle connector |
| 46A | Handle connector (die casting) |
| 47 | Locking nut |