



1	feed bar
2	blanking hole
3	oil filling port
4	plate
5	switch
6	tray
7	locking
8	T-connector
9	motor
10	power cord
11	screw
12	small shaft
13	knife
14	plate
15	bolt



15      14      13      12      11